



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PJ23HKK**

## DAF LF 260

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	26/05/2023	VIN	XLRAEL3700L522475	Axle Combi	4x4
Year	2023	Body Style	Fridge Box	Rear Suspension	Air
Mileage	150,612 Km Not Warranted	MOT Due	31/05/2026	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Tuckaway
Colour	WHITE	Gearbox	AUTOMATIC		

CARRIER SUPRA 1150MT UNIT, TWIN EVAPS, STANDBY PLUG



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Cruise control
- Front electric windows
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Screen Front  
Chipped  
Over 10mm



3: Qtr Panel nsr  
 Scratched  
 Over 25mm Thru Paint

4: Door nsr  
 Hole  
 Over 10mm



5: Door osf  
 Scratched  
 Over 25mm Not Thru Paint

6: Moulding osf Wing  
 Scratched (Painted)  
 UpTo 25mm Thru Paint

**Interior**

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** OK  
**Odour** -

Engine Runs	OK	No Excessive Smoking	OK
Turbo Boosting	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		