



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YV68MVY

Ford Transit Connect 220 1.5 ECO BLUE 100PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	22/01/2019	Colour	WHITE	CAP Average	£3,325.00
Year	2019	VIN	WF0RXXWPGRJR10566	CAP Below	£2,600.00
Mileage	118,008 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	CAP Clean	£3,850.00	Gears	6


COLLECTED AS NON-RUNNER, ENGINE ISSUES AD-BLUE, SIDE LOADING DOOR



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips

2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm

4: Panel Front
Chipped
Multiple Chips



5: Wing nsf
Chipped
Multiple Chips

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsr
Scratched
Up To 25mm Thru Paint

8: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



9: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door osf
Chipped
Edge Chip

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK