



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PK63FTZ**

## Daf LF 55.180

**Non Runner**

### Inspection

**Serious Damage?** No

### Vehicle

**VAT** Plus VAT

**V5** Buyer To Apply

### Details

**Reg. date** 17/11/2013

**VIN** XLRAE55FF0L429280

**Axle Combi** 4x2

**Year** 2013

**Body Style** Box Van

**Rear Suspension** Steel

**Mileage** 636,460 Km Not Warranted

**MOT Due** 30/06/2026

**Rear Doors** Roller

**Fuel Type** Diesel

**Cab Type** DAY CAB

**Tail Lift** Column

**Colour** ORANGE

**Gearbox** AUTOMATIC

\* NON-RUNNER, TURNS OVER DOES NOT START\*

### Tyres

**NSF** **NSI1** **NSI2** **NSI3** **NSI4**

**OSF** **OSI1** **OSI2** **OSI3** **OSI4**

**Spare** **NSO1** **NSO2** **NSO3** **NSO4**



**OSO1** **OSO2** **OSO3** **OSO4**

## Features


- Radio/CD

## Photos





## Condition Check



## Damage Photos



1: Door Moulding of  
Scuffed (Unpainted)  
Over 100mm



2: Door of  
Dented  
Over 2 Up To 10mm




3: Wing osf  
Cracked  
Replace

4: Bumper Front  
Rusted  
Over 5mm



5: Qtr Panel osr  
Rusted  
Over 5mm

6: Qtr Panel nsr  
Rusted  
Over 5mm



7: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	Service indicator light illuminated	Fault
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	Fault