



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**AV69LVD**

## Volvo FH 500

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	03/02/2020	VIN	YV2RT40C0LB305822
Year	2020	Body Style	Tractor Unit
Mileage	702,401 Km Not Warranted	MOT Due	31/07/2026
Fuel Type	Diesel	Cab Type	GLOBETROTTER CAB
Colour	WHITE	Gearbox	AUTOMATIC
		Axle Combi	6x2
		Steering Combi	Mid-Lift
		Rear Suspension	Air

### SLIDING 5TH WHEEL

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Navigation system
- Air conditioning
- Leather seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Edge Chip

2: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



3: Panel Front  
 Scratched  
 UpTo 25mm Thru Paint

4: Screen Front  
 Chipped  
 Over 10mm

**Interior**

**Carpet Condition**           OK  
**Seat Condition**            OK

**Upholstery Condition**   OK  
**Odour**                        -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		