



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DG67WRK

MAN TGS 26.360

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details			
Reg. date	11/01/2018	VIN	WMA18SZZ1JM760607
Year	2018	Body Style	Dropside & Crane
Mileage	227,918 Km Warranted	MOT Due	31/03/2026
Fuel Type	Diesel	Cab Type	DAY CAB
Colour	BLUE	Gearbox	AUTOMATIC
		Axle Combi	6x2
		Steering Combi	Rear-Lift Steer
		Rear Suspension	Air

* INPUT ERRORS ON MILEAGE HISTORY* HMF 1420 (2 EXT) REMOTE CRANE (YEAR 2017), REAR VIEW CAMERA.

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD


Photos







Condition Check




Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Door Moulding of
Scuffed (Unpainted)
Over 100mm



3: Bumper Front Moulding
Broken
Replace

4: Wing osf
Chipped
Over 5mm



5: Door osf
Dented
With Paint Damage

6: Qtr Panel osr
Dented
With Paint Damage



7: Tailgate
Rusted
Over 5mm

8: Qtr Panel nsr
Dented
With Paint Damage



9: Door Moulding nsf
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK