



COMMERCIAL VEHICLE AUCTIONS LTD  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DT69KVA**

## Vauxhall Vivaro 2900 1.5d 100PS Edition

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 31/01/2020

VIN VXEVBYHRKL7013345

CAP Below £4,525.00

Year 2020

Body Style Panel Van MWB

Gearbox MANUAL

Mileage 77,521 Miles Not Warranted

MOT Due 23/03/2026

Gears 6

Fuel Type Diesel

CAP Clean £6,450.00

CAP Average £5,675.00

Colour WHITE

\*OUTSTANDING RECALL, SIDE DOOR INOP\* TWIN SIDE LOAD DOOR, E/MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



2: Qtr Panel nsr  
Dented  
Over 30mm



3: Qtr Panel nsr  
Dented  
With Paint Damage

4: Door nsr  
Dented  
Over 30mm



5: Door osr  
Dented  
Over 30mm

6: Door osr  
Dented  
Over 30mm



7: Qtr Panel osr  
Dented  
Over 30mm

8: Qtr Panel osr  
Dented  
Over 30mm



9: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm

10: Seat Base Cover osf  
Soiled  
Heavy



11: Seat Base Cover nsf  
Soiled  
Heavy

12: Door Pad nsf  
Soiled  
Heavy

**Interior**

**Carpet Condition**  
**Seat Condition**

OK  
Poor

**Upholstery Condition**  
**Odour**

Poor  
No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		