



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
 Doncaster
 DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

C318103

MONTRACON CURTAINSIDE

Inspection		Vehicle	
VAT		Plus VAT	
V5		N/A	

Details

Reg. date		Colour	GREEN	Axle Combi	Tri
Year		VIN	10179	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

NO BRAKES, WHEEL NUTS LOOSE AND MISSING, NSF SUSPENSION MOUNT CRACKED, AXLE STRAPPED UP RAISE & LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



