



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DG16JXK

Mercedes-Benz Sprinter 516 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type	Body Style
Reg. date	11/04/2016	Diesel	Minibus
Year	2016	Colour	WHITE
Mileage	79,776 Miles Warranted	VIN	WDB906652P253267
		MOT Due	13/11/2026
		Gearbox	AUTOMATIC

15 SEATER, WHEELCHAIR LIFT

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Sill ns
Rusted
Over 5mm



7: Door nsf
Dented
Over 2 UpTo 10mm

8: Door nsf
Chipped
Edge Chip



9: Qtr Panel nsr
Dented
Over 30mm

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Rusted
Over 5mm

12: Qtr Panel osr
Dented
Over 30mm



13: Qtr Panel osr
Rusted
Over 5mm

14: Carpets Front
Holed
Over 3mm



15: Carpets Front
 Holed
 Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK