



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DG16JWP

Mercedes-Benz Sprinter 516 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type		Body Style	
Reg. date	01/05/2016	Diesel		Minibus	
Year	2016	Colour	WHITE	MOT Due	01/12/2026
Mileage	82,009 Miles Warranted	VIN	WDB9066552P252402	Gearbox	AUTOMATIC

15 SEATER, WHEELCHAIR LIFT

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Wing osf
Scratched
Over 25mm Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel osr
Rusted
Over 5mm

12: B Post os
Rusted
Over 5mm



13: Door Pad nsf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK