



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK15CFN

Mercedes-Benz Sprinter 516 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type		Body Style	
Reg. date	03/07/2015	Diesel		Minibus	
Year	2015	Colour	BLUE	MOT Due	04/12/2026
Mileage	56,646 Miles Warranted	VIN	WDB9066552P154796	Gearbox	AUTOMATIC

15 SEATER, WHEELCHAIR LIFT


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Wing osf
Dented
Over 2 UpTo 10mm



3: Bonnet
Chipped
Multiple Chips

4: Front TowEye Cvr
Missing
Replace



5: Wing nsf
Dented
With Paint Damage

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel Trim ns
Scuffed
Over 25mm

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Door nsr
Dented
With Paint Damage

14: Qtr Panel osr
Dented
Over 2 UpTo 10mm



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint

16: Qtr Panel osr
Dented
Over 2 UpTo 10mm



17: Door osf
Chipped
Edge Chip

18: Door osf
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK