



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DK15CHF**

## Mercedes-Benz Sprinter 516 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type	Body Style
Reg. date	03/07/2015	Diesel	Minibus
Year	2015	Colour	BLUE
Mileage	71,895 Miles Warranted	VIN	WDB9066552P154795
		MOT Due	31/10/2026
		Gearbox	AUTOMATIC


15 SEATER, WHEELCHAIR LIFT

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Park assist camera
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Dented  
With Paint Damage



2: Wing of  
Scratched  
Over 25mm Thru Paint



3: Bonnet  
Chipped  
Multiple Chips

4: Number Plate Front  
Broken  
Replace



5: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Thru Paint

8: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



9: Door nsf  
Dented  
With Paint Damage

10: Door nsf  
Dented  
With Paint Damage



11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

12: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



13: Qtr Panel nsr  
Dented  
With Paint Damage

14: Door osr  
Scratched  
Over 25mm Thru Paint



15: Qtr Panel osr  
Dented  
With Paint Damage

16: Door osf  
Dented  
With Paint Damage



17: Door osf  
Chipped  
Edge Chip

**Interior**

**Carpet Condition**  
**Seat Condition**

OK  
OK

**Upholstery Condition**  
**Odour**

OK  
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK