



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GK72TYV

Iveco Daily 35-140 2.3 HI-MATIC

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	15/11/2022	VIN	ZCFCL35A705510543	CAP Below	£2,900.00
Year	2022	Body Style	Panel Van	Gearbox	AUTOMATIC
Mileage	253,895 Miles Not Warranted	MOT Due	14/11/2026	Gears	8
Fuel Type	Diesel	CAP Clean	£3,825.00		
Colour	BLUE	CAP Average	£3,475.00		

WARNING LIGHTS ON DASH 3520L WB, SIDE LOAD DOOR, E/ MIRRORS

Tyres



NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking

Photos





Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Bonnet
Chipped
Multiple Chips




3: Number Plate Front
Missing
Replace

4: Bonnet
Scratched
Over 25mm Thru Paint




5: Bumper Front
Scratched
UpTo 25mm Thru Paint

6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips

8: Qtr Panel nsr
Poor Previous Repair
Poor Paint



9: Qtr Panel nsr
Dented
With Paint Damage

10: Door nsr
Dented
With Paint Damage



11: Qtr Panel osr
Chipped
Multiple Chips

12: Wing osf
Chipped
Multiple Chips



13: Door osf
Chipped
Multiple Chips

14: Door Mirror Assy osf
Broken
Replace



15: Wing osf
Chipped
Multiple Chips

16: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	Fault