



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PO69YGC**

## SCANIA R 450

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

### Details

Reg. date	25/10/2019	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Year	2019	MOT Due	31/10/2026	Axle Combi	6x2
Mileage	865,302 Km Not Warranted	CAP Clean	£18,950.00	Steering Combi	Mid-Lift
Fuel Type	Diesel	CAP Average	£17,550.00	Rear Suspension	Air
Colour	WHITE	CAP Below	£15,650.00		
VIN	YS2R6X20005569297	Cab Type	SLEEPER CAB		

\*WARNING LIGHTS ON DASH\* SLIDING 5TH WHEEL

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Panel Front  
Scratched  
Over 25mm Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Missing  
Replace

4: Door nsf  
Dented  
Over 30mm



5: Door nsf  
Dented  
With Paint Damage

6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Thru Paint

8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Door osf  
Dented  
With Paint Damage

12: Door osf  
Scratched  
Over 25mm Thru Paint



13: Door osf  
Dented  
With Paint Damage

14: Door osf  
Scratched  
Over 25mm Thru Paint



15: Screen Front  
Scratched  
Over 30mm

16: Seat Base Cover of  
Holed  
Over 3mm



17: Dash Warning Lights  
Displayed  
No Action

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		