



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PN19FVV**

## SCANIA R 450

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	19/07/2019	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Year	2019	MOT Due	31/07/2026	Axle Combi	6x2
Mileage	741,121 Km Not Warranted	CAP Clean	£20,200.00	Steering Combi	Mid-Lift
Fuel Type	Diesel	CAP Average	£18,800.00	Rear Suspension	Air
Colour	WHITE	CAP Below	£16,600.00		
VIN	YS2R6X20005559626	Cab Type	SLEEPER CAB		

\*WARNING LIGHTS ON DASH, BEARING ISSUE\* SLIDING 5TH WHEEL

### Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage

2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Missing  
Replace

4: Panel Front  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
With Paint Damage



6: Door nsf  
Dented  
With Paint Damage



7: Number Plate Rear  
Missing  
Replace

8: Qtr Panel osr  
Dented  
Over 30mm



9: Door osf  
 Scratched  
 Over 25mm Thru Paint

10: Door osf  
 Scratched  
 Over 25mm Not Thru Paint



11: Seat Base Cover osf  
 Torn  
 Over 3mm

12: Dash Warning Lights  
 Displayed  
 No Action

**Interior**

**Carpet Condition** OK  
**Seat Condition** Poor

**Upholstery Condition** OK  
**Odour** -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault		
ABS light illuminated	OK		