



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SN71YFO

Daf LF 290

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details		Colour		Gearbox	
Reg. date	14/10/2021	WHITE		MANUAL	
Year	2021	VIN	XLRAEL3700L508320	Axle Combi	4x2
Mileage	171,330 Km Not Warranted	Body Style	Hotbox	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB		




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Sill os
Dented
With Paint Damage



3: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

4: Door osf
Dented
Between 10mm + 30mm



5: Qtr Panel osr
Rusted
Over 5mm

6: Tailgate
Rusted
Over 5mm



7: Qtr Panel nsr
Rusted
Over 5mm

8: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK