



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SF640AD

Renault Master LH35 2.3 dCi 125

| Inspection | | Vehicle | |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | Present |

| Details | | | | | |
|-----------|---------------------------|------------|-------------------|---------|--------|
| Reg. date | 30/09/2014 | Colour | BLUE | Gearbox | MANUAL |
| Year | 2014 | VIN | VF1MAF4SF50868240 | Gears | 6 |
| Mileage | 99,799 Miles Warranted | Body Style | Minibus | | |
| Fuel Type | Diesel | MOT Due | 30/07/2026 | | |


12 SEATER, WHEELCHAIR ACCESS, SIDE LOAD DOOR, E/MIRRORS

| | |
|-------|-----|
| Tyres | NSF |
| NSR | |
| OSF | |
| OSR | |
| Spare | |

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Carpets Front
Torn
Over 10mm



3: Sill os
Rusted
Over 5mm

4: Bonnet
Dented
Over 30mm



5: Wing osf
Dented
With Paint Damage

6: Door nsf
Dented
With Paint Damage




7: Tailgate
Dented
With Paint Damage

8: Qtr Panel nsr
Rusted
Over 5mm



9: Door Moulding nsr
Missing
Replace

10: Door nsf
Dented
With Paint Damage



11: Wing nsf
Dented
With Paint Damage

Interior

| Carpet Condition | Average | Upholstery Condition | Average |
|--------------------------|---------|--|---------|
| Seat Condition | Average | Odour | No |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |

Windows

OK

Radio

OK

Steering

OK