



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WX14AEG

FORD TRANSIT T350 2.2 TDCI125PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	17/03/2014	VIN	WF0XXTTFXDD14617	CAP Below	£1,150.00
Year	2014	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	96,925 Miles Warranted	MOT Due	16/03/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£2,125.00		
Colour	WHITE	CAP Average	£1,650.00		

COLLECTED AS NON-RUNNER, ACCIDENT DAMAGE, REAR DIFF, DPF & AIR SUSPENSION REQUIRE ATTENTION, AIR BAGS DEPLOYED, UNABLE TO ACCESS BONNET, WARNING LIGHTS ON DASH SIDE LOAD DOOR, TOW BAR, ROOF RACK, E/ MIRRORS, HEATED WINDSCREEN, RACKING IN REAR, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Unclassified
Substantial Accident Damage
Report Only

2: Door nsf
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Rusted
Over 5mm

4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Dented
With Paint Damage

6: Wing osf
Rusted
Over 5mm



7: Door Mirror Assy osf
Broken
Replace

8: Screen Front
Chipped
Over 10mm



9: Other
N/A
N/A

10: Carpets Front
Holed
Over 3mm



11: Seat Belt of
Broken
Replace

12: Dash Warning Lights
Displayed
No Action



13: Roof Lining
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Poor
OK

Upholstery Condition
Odour

Poor
-

Engine Runs	Fault	No Excessive Smoking	OK
EML light illuminated	Fault		
Airbag light illuminated	Fault		
ABS light illuminated	OK		
		Radio	Fault
		Steering	Fault