



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**SP63HZC**

## Ford Transit T300 TDCi 100PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	30/09/2013	VIN	WFOXXXTTFXDP43416	CAP Below	£775.00
Year	2013	Body Style	Panel Van MWB	Gearbox	MANUAL
Mileage	75,190 Miles Warranted	MOT Due	06/09/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£1,475.00		
Colour	WHITE	CAP Average	£1,175.00		

SIDE LOAD DOOR, ROOF RACK

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

## Features


- Radio/CD
- Front electric windows
- Central locking

## Photos





## Condition Check




## Damage Photos



1: Sill os  
Rusted  
Over 5mm

2: Roof  
Rusted  
Over 5mm



3: Bonnet  
Dented  
With Paint Damage

4: Wing of  
Dented  
With Paint Damage



5: Door of  
Rusted  
Over 5mm

6: B Post of  
Rusted  
Over 5mm



7: Qtr Panel of  
Rusted  
Over 5mm


8: Tailgate  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Rusted  
Over 5mm



10: Door nsr  
Dented  
With Paint Damage



11: Sill ns  
Rusted  
Over 5mm



12: Door nsr  
Dented  
With Paint Damage



13: B Post ns  
Rusted  
Over 5mm



14: Door nsf  
Rusted  
Over 5mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Poor	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
Airbag light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK