



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ70ZFP

Daf XF 480

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	15/02/2021	VIN	XLRTGH4300G341924	Axle Combi	6x2
Year	2021	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	590,936 Km Warranted	MOT Due	28/02/2027	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SURROUND CAMERA SYSTEM, SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Electric sunroof
- Cloth seat trim
- Air conditioning


Photos







Model	DAF XF480 FTG		Speed Limit	N
Year of Manufacture	15/02/21		2020	
ARTIC R				
Description of Weights	15000	27000	4500	4500
Max Weight	44000	80000		
Max Weight	44000	80000		
Max Weight	8000	8000		
Max Weight	7800	7800		
Max Weight	11500	11500		

DEPARTMENT FOR TRANSPORT GREAT BRITAIN
REPLACEMENT




DAF TRUCKS N.V.			
GB			
	23700	kg	1
1 -	44000	kg	2
2 -	8000	kg	3
3 -	7500	kg	4
4 -	11500	kg	T
T -	19000	kg	

Type
Motor no.





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips



3: Moulding nsf Wing
Broken
Replace



4: Door nsf
Scratched
Up To 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: Qtr Panel nsr
Rusted
Over 5mm




7: Qtr Panel nsr
Cracked
Replace



8: Qtr Panel osr
Cracked
Replace





9: Qtr Panel osr
Rusted
Over 5mm

10: Door osf
Scratched
UpTo 25mm Thru Paint



11: Handle Inner osf
Damaged
Replace

12: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		