



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ70ZFR

Daf XF 480

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	15/02/2021	VIN	XLRTGH4300G341925	Axle Combi	6x2
Year	2021	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	408,606 Km Warranted	MOT Due	31/03/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SPACE CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

WARNING LIGHTS ON DASH SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Electric sunroof
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos








Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Screen Front
Cracked
Replace



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Chipped
Multiple Chips




5: Bumper Front
Dented
With Paint Damage



6: Qtr Panel nsr
Rusted
Over 5mm



7: Qtr Panel osr
Cracked
Replace



8: Qtr Panel osr
Rusted
Over 5mm





9: Door osf
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		