



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BF68GCU

Daf LF 230

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	06/12/2018	Colour	WHITE	Cab Type	DAY CAB
Year	2018	VIN	XLRAEL3700L479287	Gearbox	MANUAL
Mileage	197,928 Km Not Warranted	Body Style	Hotbox	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	Expired		

WARNING LIGHT ON DASH ECON TWIN COMPARTMENT BODY



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD


Photos







Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Door Moulding of
Scuffed (Unpainted)
Over 100mm



3: Door osf
Dented
With Paint Damage

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Qtr Panel osr
Rusted
Over 5mm



7: Qtr Panel nsr
Rusted
Over 5mm

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door Moulding nsf
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK