



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

2625588

Iveco Eurocargo 120E21

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	25/08/2014	VIN	ZCFAF1EF102625588	Axle Combi	4x2
Year	2014	Body Style	Box Van	Rear Suspension	Steel
Mileage	69,192 Km Warranted	MOT Due	31/10/2026	Rear Doors	Roller
Fuel Type		Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	AUTOMATIC		

MOD654 FORM T/F


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Screen Front
Chipped
Over 10mm

4: Door nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

6: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



7: Panel Front
Cracked
Replace

8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		