



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CU21HSZ

Ford Transit 2.0 EcoBlue 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	03/03/2021	VIN	WFOCXTTTRCLS18591	CAP Below	£7,650.00
Year	2021	Body Style	Tipper	Gearbox	MANUAL
Mileage	78,294 Miles Not Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£10,400.00		
Colour	WHITE	CAP Average	£9,300.00		

WARNING LIGHTS ON DASH TOW BAR, AD-BLUE.



Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm

2: Bonnet
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Wing osf
Dented
With Paint Damage



5: Flasher Side Repeater os
Broken
Replace

6: Door osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage

8: Tailgate
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
With Paint Damage

10: Door nsr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK