



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PK67VDO

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

VIN XLRTEM4100G181959

Gearbox AUTOMATIC

Year 2017

Body Style Tractor Unit

Axle Combi 4x2

Mileage 1,053,050 Km
Warranted

Service history Yes

Rear Suspension Air

MOT Due 31/07/2026

Fuel Type Diesel

Cab Type SLEEPER CAB

Colour RED

COLLECTED AS NON-RUNNER, CAMS, ROCKERS & SHELLS REQUIRE ATTN

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips

2: Bumper Front
Poor Previous Repair
Poor Colour



3: Bonnet
Chipped
Multiple Chips

4: Screen Front
Chipped
UpTo 10mm



5: Wing nsf
Chipped
Multiple Chips

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Fog Lamp Surround ns
Scratched (Painted)
UpTo 25mm Thru Paint

8: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm

10: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



11: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint

12: Door Pad osf
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK