



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK62WYR

Mercedes-Benz Axor 1843

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	22/10/2012	Colour	WHITE	Gearbox	AUTOMATIC
Year	2012	VIN	WDF9440322B977549	Axle Combi	4x2
Mileage	627,254 Km Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	31/08/2026		

SLIDING 5TH WHEEL.

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Door Moulding of
Scuffed (Unpainted)
Over 100mm



3: Bumper Front
Rusted
Over 5mm

4: Door osf
Dented
With Paint Damage



5: Qtr Panel Moulding os
Broken
Replace

6: B Post os
Rusted
Over 5mm



7: Qtr Panel Moulding os
Broken
Replace

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK