



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SK21CGV

Scania R 450

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	24/05/2021	VIN	YS2R6X20009285444	Axle Combi	6x2
Year	2021	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	687,718 Km Not Warranted	MOT Due	30/04/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	HIGHLINE CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SLIDING 5TH WHEEL, TWIN FUEL TANKS

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Manual sunroof
- Leather seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Over 10mm



3: Wing nsf
Dented
With Paint Damage

4: Door nsf
Chipped
Multiple Chips



5: Door Mirror Assy nsf
Broken
Replace

6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door osf
Chipped
Multiple Chips



9: Wing ofsf
Chipped
Multiple Chips

10: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		