



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

NJ19AYP

Fuso Canter 7C15

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	30/03/2019	Colour	GREEN	Cab Type	CREW CAB
Year	2019	VIN	TYAFEB74ERDZ12901	Gearbox	AUTOMATIC
Mileage	75,282 Km Warranted	Body Style	Tipper	Axle Combi	4x2
Fuel Type	HYBRID	MOT Due	30/06/2026	Rear Suspension	Steel

STEEL BODY, SURROUND CAMERA SYSTEM

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door nsf
Scratched
Over 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint

4: B Post ns
Scratched
Over 25mm Thru Paint



5: Door osf
Scratched
Over 25mm Thru Paint

6: Door Pad osf
Soiled
Heavy



7: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

Poor
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		