



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ70ZFV

DAF XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	15/02/2021	VIN	XLRTGH4300G342150	Axle Combi	6x2
Year	2021	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	448,100 Km Warranted	MOT Due	28/02/2027	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SPACE CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SURROUND CAMERA SYSTEM, SLIDING 5TH WHEEL

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Chipped
Multiple Chips

4: Bumper Front Moulding
Broken
Replace



5: Wing nsf
Hole
Over 10mm

6: Bumper Front
Dented
With Paint Damage



7: Wing Front Arch Extension ns
Broken
Replace

8: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



9: Qtr Panel nsr
Rusted
Over 5mm

10: Panel Rear
Cracked
Replace



11: Qtr Panel Arch Extension os
Broken
Replace

12: Panel Rear
Cracked
Replace



13: Qtr Panel osr
Rusted
Over 5mm

14: Door osf
Chipped
Multiple Chips



15: Door Mirror Assy nsf
Broken
Replace

16: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition Poor
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		