



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MX64AKG

Mercedes-Benz Actros

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/09/2014

Year 2014

Mileage 174,145 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9630032L867775

Body Style Box Van

MOT Due 31/10/2026

Cab Type CLASSICSPACE CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

Tail Lift Cantilever

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Bumper Front
Scratched
Over 100mm Thru Paint




5: Bumper Front Moulding
Broken
Replace

6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Wing nsf
Chipped
Multiple Chips

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Bumper Front Moulding
Broken
Replace

10: Door osf
Chipped
Multiple Chips



11: Screen Front
Cracked
Replace

Interior

Carpet Condition
Seat Condition

OK
OK

Upholstery Condition
Odour

OK
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		