



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**BC15AHZ**

## Iveco Daily 70-170

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 To Follow

### Details

Reg. date	27/07/2015	Colour	WHITE	Service documents	Printout
Year	2015	VIN	ZCFC270C905038462	Gearbox	MANUAL
Mileage	91,279 Miles Warranted	Body Style	Panel Van LWB		
Fuel Type	Diesel	Service history	Yes		

SIDE LOAD DOOR, TACHO, COMPRESSOR GENERATOR EQUIPMENT, PENNY KJ150 HYDROLIC SWING LIFT, GARDNER DENVER CABLE WINCH, MICROWAVE, HOT WATER SUPPLY, TOW BAR.

### Tyres

NSF
NSR
OSF
OSR
Spare

## Features

- Radio/CD
- Front electric windows
- Central locking


## Photos







## Condition Check



## Damage Photos




1: Seat Base Cover of  
Torn  
Over 3mm

2: Bonnet  
Dented  
With Paint Damage



3: Bonnet  
Missing  
Replace

4: Wing osf  
Dented  
With Paint Damage



5: Door osf  
Dented  
With Paint Damage

6: Qtr Panel osr  
Dented  
With Paint Damage



7: Tailgate  
Dented  
With Paint Damage

8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Door nsf  
Dented  
With Paint Damage

10: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

### Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK