

VEHICLE INSPECTION REPORT

NX19YOT

Peugeot Expert 1200 1.6 BLUEHDi 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/03/2019

Year 2019

Mileage 123,461 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3VBBHVBKZ018080

Body Style Panel Van LWB

MOT Due 11/02/2026

CAP Clean £3,875.00

CAP Average £3,400.00

CAP Below £2,700.00

Gearbox MANUAL

Gears 5

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, ROOF RACKPOWER INVERTER, PIPE STORAGE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Rear parking sensor
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
With Paint Damage



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Chipped
Multiple Chips



5: Door nsr
Dented
Over 30mm



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door osr
Scratched
Over 25mm Thru Paint



8: Door osr
Chipped
Multiple Chips



9: Qtr Panel osr
Chipped
Multiple Chips



10: Qtr Panel osr
Chipped
Multiple Chips



11: Screen Front
Chipped
Over 10mm



12: Seat Base Cover nsf
Soiled
Heavy



13: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		