



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CV63GZD

Ford Transit T350 TDCi 125ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	28/01/2014	VIN	WF0XXTTFXDC64658	CAP Below	£980.00
Year	2014	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	125,270 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£1,850.00		
Colour	WHITE	CAP Average	£1,450.00		

WARNING LIGHT ON DASH, SMOKING SIDE LOAD DOOR, TOW BAR, ROOF RACK, DEADLOCKS, INVERTER, LADDER STOW, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres



NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos








Condition Check



Damage Photos



1: Roof
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Wing nsf
Dented
With Paint Damage

4: Sill ns
Rusted
Over 5mm



5: Door nsf
Chipped
Multiple Chips

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
Over 30mm

8: Qtr Panel nsr
Dented
Over 30mm



9: C Post ns
Dented
With Paint Damage

10: C Post ns
Dented
With Paint Damage



11: Door nsr
Dented
Over 30mm

12: Door osr
Dented
With Paint Damage



13: C Post os
Dented
Over 30mm

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint

16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Dented
With Paint Damage

18: Door osf
Dented
With Paint Damage



19: Door Pad osf
Soiled
Heavy

20: Carpets Front
Holed
Over 3mm



21: Fascia Panel
Broken
Replace

22: Seat Base Cover nsf
Soiled
Heavy



23: Fascia Panel
Broken
Replace

24: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition Poor
Seat Condition Poor

Upholstery Condition Poor
Odour No

Engine Runs	Fault	No Excessive Smoking	Fault
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		