



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MT23KHW

Volkswagen Id.3 58kWh

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	13/04/2023	VIN	WVWZZZE1ZPP043248	CAP Below	£12,500.00
Year	2023	Body Style	Hatchback	Gearbox	AUTOMATIC
Mileage	10,137 Miles Not Warranted	MOT Due	12/04/2026	Gears	1
Fuel Type	Electric	CAP Clean	£14,800.00	Doors	5
Colour	BLUE	CAP Average	£13,600.00		

KEYLESS IGNITION, PRIVACY GLASS, REAR VIEW CAMERA, DUAL ZONE CLIMATE CONTROL, HEAD UP DISPLAY, PANORAMIC ROOF

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Front parking sensor
- Body coloured bumpers
- Front electric windows
- Navigation system
- Electric door mirrors
- Alloy wheels
- Rear parking sensor
- Air conditioning
- Spare wheel
- Radio/CD
- Climate control

Photos





Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Thru Paint

2: Wing osf
Scratched
Over 25mm Not Thru Paint

No Image



3: Wing nsf
Scratched
Over 25mm Thru Paint

4: Bumper Rear
Chipped
1 To 5

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		