

VEHICLE INSPECTION REPORT

NX19YOY

Peugeot Expert 1200 1.6 BLUEHDi 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 20/03/2019

Year 2019

Mileage 64,972 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3VBBHVBKZ018083

Body Style Panel Van LWB

MOT Due 10/01/2026

CAP Clean £5,750.00

CAP Average £5,050.00

CAP Below £4,025.00

Gearbox MANUAL

Gears 5

AD-BLUE, TWIN SIDE LOAD DOOR, ROOF RACK, E/ MIRRORS, POWER INVERTER 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Cruise control
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wings
Scratched
Over 25mm Not Thru Paint



3: Door nsf
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel nsr
Chipped
Multiple Chips



5: Bumper Rear
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel osr
Dented
With Paint Damage



7: Door Pad osf
Soiled
Heavy



8: Seat Base Cover osf
Torn
Over 3mm



9: Seat Base Cover nsf
Soiled
Heavy



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK