



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20TCO

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	31/07/2020	VIN	W1V9106332P251467	CAP Below	£9,625.00
Year	2020	Body Style	Panel Van L2	Gearbox	AUTOMATIC
Mileage	76,299 Miles Warranted	MOT Due	06/08/2026	Gears	9
Fuel Type	Diesel	CAP Clean	£13,700.00		
Colour	WHITE	CAP Average	£12,050.00		

AD-BLUE, SIDE LOADING DOOR

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Wing of
Scratched
Over 25mm Thru Paint



3: Bonnet
Scratched
Over 25mm Not Thru Paint

4: Bonnet
Dented
Between 10mm + 30mm



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Other
N/A
N/A

8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm




9: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

10: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

12: Qtr Panel nsr
Dented
With Paint Damage



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Door nsr
Scratched
Over 25mm Not Thru Paint

16: Badgedecal Rear
Missing
Replace



17: Door nsr
Chipped
Edge Chip

18: Door osr
Dented
Between 10mm + 30mm



19: Door osr
Dented
With Paint Damage

20: Door osr
Scratched
Over 25mm Not Thru Paint



21: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

22: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



23: Qtr Panel osr
Chipped
1 To 5

24: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK