



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20RXZ

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	31/07/2020	VIN	W1V9106332P252120	CAP Below	£10,050.00
Year	2020	Body Style	Panel Van L2	Gearbox	AUTOMATIC
Mileage	68,472 Miles Warranted	MOT Due	22/07/2026	Gears	9
Fuel Type	Diesel	CAP Clean	£14,350.00		
Colour	WHITE	CAP Average	£12,600.00		

AD-BLUE, SIDE LOADING DOOR


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm




3: Wing nsf
Dented
With Paint Damage

4: Wing nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Sill ns
Dented
With Paint Damage





7: Door nsr
Scratched
Over 25mm Not Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Badgedecal Rear
Missing
Replace



13: Door osr
Dented
Between 10mm + 30mm

14: Door osr
Dented
Between 10mm + 30mm



15: Door osr
Dented
Between 10mm + 30mm

16: Door nsr
Chipped
Edge Chip



17: Door osr
Chipped
Edge Chip

18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

20: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



21: Qtr Panel osr
Dented
Over 30mm

22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Door osf
Chipped
Edge Chip

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK