



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BK72UXF

Mercedes-Benz Sprinter 315 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	07/12/2022	VIN	W1V9076332P522817	CAP Below	£15,700.00
Year	2022	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	38,637 Miles Not Warranted	MOT Due	06/12/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£20,550.00		
Colour	WHITE	CAP Average	£18,700.00		

AD-BLUE, SIDE LOADING DOOR

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel nsr
 Scratched
 Over 25mm Not Thru Paint

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK