

VEHICLE INSPECTION REPORT

NX19ZXS

Peugeot Expert 1200 1.6 BLUEHDi 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/03/2019

Year 2019

Mileage 35,714 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3VBBHVBKZ018082

Body Style Panel Van LWB

MOT Due 18/03/2026

CAP Clean £6,925.00

CAP Average £6,100.00

CAP Below £4,875.00

Gearbox MANUAL

Gears 5

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Auxiliary input socket
- Passenger airbag
- Cruise control
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Qtr Panel osr
Dented
Over 30mm



4: Door Pad osf
Soiled
Heavy



5: Seat Base Cover nsf
Soiled
Heavy



6: Fascia Panel
Soiled
Heavy



7: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		