

VEHICLE INSPECTION REPORT

YE19ALD

Daf CF 410

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Missing

Details

Reg. date 26/07/2019

Year 2019

Mileage 186,164 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRADM4100G263603

Body Style Tipper

MOT Due Expired

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

WARNING LIGHT ON DASH PALFINGER EPSILON M125L CLASSIC CRANE (YEAR 2019), THOMPSONS STEEL BODY TIPPING GEAR, SHEETING SYSTEM


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Manual sunroof
- Central locking
- Park assist camera
- Air conditioning
- Cloth seat trim
- Digital radio
- Front electric windows
- Radio/CD
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Grille Front
Broken
Replace



3: Door osf
Scratched
Over 25mm Thru Paint



4: Panel Rear
Dented
Over 30mm



5: Panel Rear
Dented
With Paint Damage



6: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	Fault			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	Fault		
ABS light illuminated	OK			Service indicator light illuminated	OK		

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK