



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PK70EKZ

DAF CF 340

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	17/02/2021	Colour	GREEN	Gearbox	AUTOMATIC
Year	2021	VIN	XLRASM4100G317565	Axle Combi	6x2
Mileage	274,091 Km Warranted	Body Style	Beavertail		
Fuel Type	Diesel	Cab Type	DAY CAB		

WARNING LIGHTS ON DASH *REQUIRES WORK TO PASS MOT, NUMEROUS SMALL PROBLEMS & PINS LOOSE UNDER BODY*CHEESE WEDGE BODY, WINCH, SURROUND CAMERA SYSTEM, REAR LIFT


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Manual sunroof
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm

2: Dash Warning Lights
Displayed
No Action



3: Seat Base Cover nsf
Holed
Over 3mm

4: Bonnet
Chipped
Multiple Chips



5: Screen Front
Chipped
Over 10mm

6: Bumper Front
Dented
With Paint Damage



7: Fogdriving Lamp nsf
Broken
Replace

8: Door nsf
Dented
With Paint Damage



9: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint

10: Door osf
 Dented
 With Paint Damage



11: Door osf
 Chipped
 Multiple Chips

12: Door Mirror Assy nsf
 Broken
 Replace

Interior

Carpet Condition Poor
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		