



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | [cva.noreply@cva-auctions.co.uk](mailto:cva.noreply@cva-auctions.co.uk)

# VEHICLE INSPECTION REPORT

**LN67ACO**

## Daf LF 150

### Inspection

**Serious Damage?** No

### Vehicle

**VAT** Plus VAT  
**V5** Present

### Details

<b>Reg. date</b>	22/12/2017	<b>Colour</b>	WHITE	<b>Cab Type</b>	DAY CAB
<b>Year</b>	2017	<b>VIN</b>	XLRAEL1500L467975	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	92,692 Km Not Warranted	<b>Body Style</b>	Sweeper	<b>Axle Combi</b>	4x2
<b>Fuel Type</b>	Diesel	<b>MOT Due</b>	30/09/2026	<b>Rear Suspension</b>	Steel

\*WARNING LIGHT ON DASH\* SCARAB BODY, 4,888 SWEEPING HOURS, 8,534 TOTAL RUNNING HOURS

### Tyres



<b>NSF</b>	<b>NSI1</b>	<b>NSI2</b>	<b>NSI3</b>	<b>NSI4</b>
<b>OSF</b>	<b>OSI1</b>	<b>OSI2</b>	<b>OSI3</b>	<b>OSI4</b>
<b>Spare</b>	<b>NSO1</b>	<b>NSO2</b>	<b>NSO3</b>	<b>NSO4</b>
	<b>OSO1</b>	<b>OSO2</b>	<b>OSO3</b>	<b>OSO4</b>

## Features


- Air conditioning

## Photos





## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



3: Bumper Front  
Scratched  
Over 100mm Thru Paint

4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

6: Wing Front Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Thru Paint

8: Door nsf  
Chipped  
Edge Chip



9: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

10: Wing Front Arch Extension os  
Scratched (Painted)  
Over 25mm Thru Paint

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK