



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BD64DTX

Iveco Daily 50C15

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	28/10/2014	VIN	ZCFC50A400D520068
Year	2014	Body Style	Access Platform
Mileage	271,807 Km Warranted	Service history	Yes
Fuel Type	Diesel	MOT Due	28/02/2027
Colour	WHITE	Cab Type	DAY CAB
		Gearbox	MANUAL
		Axle Combi	4x2
		Rear Suspension	Steel

PTO DOES NOT ENGAGE, BASKET MISSING FOR PLATFORM VERSALIFT EUROTEL 38LF PLATFORM





Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing of
Dented
With Paint Damage



2: Front TowEye Cvr
Missing
Replace



3: Bonnet
Chipped
Multiple Chips



4: Bonnet
Scratched
Over 25mm Not Thru Paint



5: Bumper Front
Hole
UpTo 25mm



6: Door Mirror Assy nsf
Broken
Replace



7: Wing nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door Lock nsf
Broken
Replace

10: Door nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel nsr
Dented
With Paint Damage

14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Door Lock osf
Broken
Replace

18: Door osf
Dented
With Paint Damage



19: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK