



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

EX22HXC

Scania G 410 XT

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	01/04/2022	VIN	YS2G8X40005649039	CAP Below	£47,300.00
Year	2022	Body Style	Tipper	Cab Type	SLEEPER CAB
Mileage	273,601 Km Not Warranted	MOT Due	30/04/2026	Gearbox	AUTOMATIC
Fuel Type	Diesel	CAP Clean	£55,900.00	Axle Combi	8x4
Colour	WHITE	CAP Average	£53,700.00		

WARNING LIGHT ON DASH SHEETING SYSTEM, ABBA PREDATOR ULTIMATE BODY, HYVA TIPPING GEAR

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos




1: Wing of
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wing nsf
Chipped
Multiple Chips

4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Broken
Replace

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

8: Door osf
Chipped
Edge Chip



9: Screen Front
 Chipped
 Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK