



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

EX22HXA

Scania G 410 XT

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	14/03/2022	Colour	WHITE	Cab Type	SLEEPER CAB
Year	2022	VIN	YS2G8X40005649109	Gearbox	AUTOMATIC
Mileage	278,958 Km Not Warranted	Body Style	Tipper	Axle Combi	8x4
Fuel Type	Diesel	MOT Due	31/03/2026	Rear Suspension	Steel

WARNING LIGHT ON DASH ABBA PREDATOR ULTIMATE BODY, HYVA TIPPING GEAR, SHEETING SYSTEM, SURROUND CAMERA SYSTEM


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Scratched
Over 25mm Not Thru Paint

6: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK