

VEHICLE INSPECTION REPORT

YF71VHR

Mercedes-Benz Sprinter 3.5 PROGRESSIVE

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/02/2022

Year 2022

Mileage 78,775 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P430178

Body Style Panel Van L3

CAP Clean £14,600.00

CAP Average £13,500.00

CAP Below £11,650.00

Gearbox MANUAL

Axle Combi 4x2

AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- USB/iPod interface
- Cloth seat trim
- Cruise control
- Front electric windows
- Navigation system
- Drivers airbag
- Auxiliary input socket
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Wing osf
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door Mirror Assy osf
Broken
Replace



5: Door osf
Scratched
Over 25mm Thru Paint



6: Panel Rear
Scratched
Over 25mm Thru Paint



7: Sill os
Dented
With Paint Damage



8: Sill Panel Trim os
Scuffed (Unpainted)
Over 100mm



9: Panel Rear
Dented
Between 10mm + 30mm



10: Door osr
Dented
With Paint Damage



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Badgedecal Rear
Missing
Replace



13: Door nsr
Dented
Over 30mm



14: Sill Panel Trim ns
Scuffed (Unpainted)
Over 100mm



15: Panel Rear
Scratched
Over 25mm Thru Paint



16: Sill ns
Dented
Over 30% Of Panel



17: Panel Front
Scratched
Over 25mm Not Thru Paint



18: Panel Front
Dented
With Paint Damage



19: Handle Outer nsf
Scratched (Painted)
Over 25mm Thru Paint



20: Carpets Front
Holed
Over 3mm



21: Seat Base Cover osf
Soiled
Light

22: Seat Base Cover osf
Soiled
Light

Interior

Carpet Condition	Average	Upholstery Condition	OK
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK