

VEHICLE INSPECTION REPORT

PO18RYH

Daf CF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	25/05/2018	Colour	RED	Cab Type	DAY CAB
Year	2018	VIN	XLRAEM3700G183334	Gearbox	AUTO
Mileage	424,093 Km Warranted	Body Style	Curtainside	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/04/2026	Tail Lift	Column

DAY CAB, A/C, COLUMN TAIL LIFT, ROLLER DOOR, SURROUND CAMERA SYSTEM, REAR VIEW CAMERA BEEN ON FULL R&M CONTRACT FROM NEW

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK