



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DK61YOD**

## Mercedes-Benz Axor 1843

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	21/09/2011	Colour	WHITE	Cab Type	HIGH ROOF SLEEPER CAB
Year	2011	VIN	WDF9440322B974546	Gearbox	AUTOMATIC
Mileage	1,463,047 Km Not Warranted	Body Style	Tractor Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/07/2026	Rear Suspension	Air

\*MILEAGE DISCRPENY ON MOT\* SLIDING 5TH WHEEL


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wing nsf  
Scratched  
Over 25mm Thru Paint

4: Qtr Panel Trim ns  
Broken  
Replace



5: Panel Rear  
Dented  
With Paint Damage

6: Qtr Panel Trim os  
Broken  
Replace



7: Door osf  
Scratched  
Over 25mm Thru Paint

8: Screen Front  
Chipped  
Over 10mm



9: Seat Base Cover of  
Torn  
Over 3mm

**Interior**

**Carpet Condition**

OK

**Upholstery Condition**

OK

**Seat Condition**

Poor

**Odour**

-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		