



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DE64CZK**

## MAN TGS 18.400

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Colour	Cab Type
Reg. date	01/12/2014	WHITE	SLEEPER CAB
Year	2014	VIN	WMA06SZZ8FM664868
Mileage	1,296,967 Km Not Warranted	Body Style	Tractor Unit
Fuel Type	Diesel	MOT Due	31/10/2026
		Gearbox	AUTOMATIC
		Axle Combi	4x2
		Rear Suspension	Air

\*WARNING LIGHTS ON DASH\*




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Panel Front  
Scratched  
Over 25mm Thru Paint

2: Panel Front  
Scratched  
Over 25mm Thru Paint



3: Wing nsf  
Scratched  
Over 25mm Thru Paint

4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel nsr  
Chipped  
Multiple Chips

6: Qtr Panel Trim ns  
Scuffed  
Over 25mm



7: Qtr Panel Trim os  
Scuffed  
Over 25mm

8: Door osf  
Dented  
With Paint Damage



9: Wing of  
Scratched  
Over 25mm Thru Paint

10: Screen Front  
Chipped  
Over 10mm



11: Dash Warning Lights  
Displayed  
No Action

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK