



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**BD150CZ**

## Iveco Daily 70-170

### Inspection

**Serious Damage?** No

### Vehicle

**VAT** Plus VAT  
**V5** Present

### Details

<b>Reg. date</b>	24/05/2015	<b>Colour</b>	WHITE	<b>Service documents</b>	Printout
<b>Year</b>	2015	<b>VIN</b>	ZCFC270C705011082	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	85,602 Miles Warranted	<b>Body Style</b>	Panel Van LWB		
<b>Fuel Type</b>	Diesel	<b>Service history</b>	Yes		

TACHO – 137766 KM'S', SIDE LOAD DOOR, PENNY KJ150 HYDROLIC SWING LIFT, GARDNER DENVER CABLE WINCH, MICROWAVE, HOT WATER SUPPLY, TOW BAR.

### Tyres

NSF
NSR
OSF
OSR
Spare

## Features


- Radio/CD
- Front electric windows
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover of  
Torn  
Over 3mm

2: Bonnet  
Dented  
With Paint Damage



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

4: Qtr Panel osr  
Dented  
Over 30mm



5: Tailgate  
Dented  
With Paint Damage

6: Door nsf  
Dented  
With Paint Damage

**Interior**

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK