



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YP69ZHL

Ford Ranger 2.0 EcoBlue 170PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details			
Reg. date	25/11/2019	VIN	6FPPXXMJ2PKT46398
Year	2019	Body Style	Pickup Double Cab
Mileage	129,517 Miles Warranted	MOT Due	29/01/2027
Fuel Type	Diesel	CAP Clean	£6,600.00
Colour	WHITE	CAP Average	£5,700.00
		CAP Below	£4,450.00
		Gearbox	MANUAL
		Gears	6

COLLECTED AS NON RUNNER- NEEDS NEW ENGINE


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
UpTo 25mm Not Thru Paint

2: Bumper Front
Scratched
Over 25mm Not Thru Paint




3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
Over 2 UpTo 10mm

6: Qtr Panel osr
Dented
With Paint Damage



7: Lamp osr
Broken
Replace

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Engine Runs Fault